

South East Radio Group

PO Box 1103
Mount Gambier. 5290

President: Nick Somerville. VK5NJS
Secretary: Col Huon. VK5HCF



Repeater report 17 July 2026

Plenty of action behind the scenes but not visibly.

During last week Norbert installed the new power measuring device but due to a router problem it has not been available to view from our phones. Nick has that in hand and we hope to have a new router working by the time we meet.

I've also had to do a little software work but that is now complete and just requires loading onto the device at VK5RMG.

Members may have noticed that signals from the northern connections is often noisy. Peter VK5BE has some ideas in mind. This is a result of the radio path between Naracoorte and Willalooka suffering because of the ridges and trees in between.

In addition we need to get on with the replacement battery for Mt Benson. It may require a battery charger as well if we go for a Lithium Iron Phosphate rather than lead acid battery.

John VK5DJ